


Patch Meadow Lane / Rutland Street / North Road



Stats:
 22 parcels
 73.69 acres
 ~4.5 miles to North Billerica MBTA Station

Why Here?
 -Access to collector road: Rte 4
 -Reduced disturbance: semi-disturbed land with younger woods
 -Older structures that may be redeveloped
 -Limited wetlands and wetlands buffers
 -Good geology & supportive soils: limited ledge, glacial stratified deposits
 -Balance of preservation & development: near Great Brook Farm State Park

Legend

- Properties under Consideration
- CARLISLE PARCELS 2021
- Structures
- Conservation Restriction
- DEP Wetlands

Open Space - Ownership

- Carlisle Conservation Foundation
- Commonwealth of MA
- Town of Carlisle - Conservation Commission

Basemap: USGS Surficial Geology

- Orange/Blue = Glacial Stratified Deposits (good)
- Off-White/Green = Glacial Till Deposits (not good)
- Red Stripes = Bedrock Outcrops / Ledge (not good)
- Brown/Lime/Purple/Pink = Postglacial Deposits (not good)

